



# AVIATION ENGINE SERVICE, INC.

## JET ENGINE OVERHAUL P&W JT3D - JT3D

FAA Approved Repair Station No. ENVR123K - EASA.145.4204

Venezuela INAC Approved Repair Station TMAV-E # 254

Argentina DNA Approved Repair Station No. 1-B-371

8050 N.W. 90th Street, Miami, Florida 33166

### ENGINE LIFE LIMITED COMPONENT RECORD

WORK ORDER 6404	MODEL JT3D-7	ESN 669510	DATE June 16, 2009
TOTAL TIME 43,531.00	CUSTOMER M.C.A.		TOTAL CYCLES 16,547

#### N-1 COMPRESSOR DISKS

STG	PART NUMBER	SERIAL NUMBER	LIMIT HRS	TOTAL HOURS	REMAIN HOURS	LIMITS CYCLES	TOTAL CYCLES	REMAIN CYCLES
C-1	746441	G77671	N/A	N/A	N/A	14,000	3,537	10,463
C-2	728202	6A4433	N/A	N/A	N/A	20,000	10,055	9,945
C-4	719404	H54585	N/A	N/A	N/A	30,000	6,119	23,881
C-5	719505	H54434	N/A	N/A	N/A	30,000	6,119	23,881
C-6	719606	H53754	N/A	N/A	N/A	30,000	6,119	23,881
C-7	726907	4A9359	N/A	N/A	N/A	30,000	10,055	19,945
C-8	719608	H53688	N/A	N/A	N/A	30,000	6,119	23,881
C-9	719409	H37965	N/A	N/A	N/A	30,000	6,119	23,881

#### N-2 COMPRESSOR DISKS

C-10	701810	H39367	N/A	N/A	N/A	23,000	6,119	16,881
C11	762411	MENCAH2614	N/A	N/A	N/A	30,000	818	29,182
C-12	762412	MENCAH4004	N/A	N/A	N/A	30,000	818	29,182
C-13	762413	MENCAH2059	N/A	N/A	N/A	30,000	818	29,182
C-14*	750414	TBA	N/A	N/A	N/A	30,000	0	30,000
C-15*	750415	TBA	N/A	N/A	N/A	30,000	0	30,000
C-16	739216	S682282	N/A	N/A	N/A	22,000	818	21,182

#### TURBINE DISKS

T-1	416301	OT9684	N/A	N/A	N/A	16,000	6,326	9,674
T-2	757602	H05688	N/A	N/A	N/A	16,000	8,286	7,714
T-3*	797903	TBA	N/A	N/A	N/A	12,000	0	12,000
T-4*	771104	TBA	N/A	N/A	N/A	20,000	0	20,000

#### DRIVE SHAFTS

HPTS	699356	0V2241	N/A	N/A	N/A	24,000	15,625	8,375
LPTS	671023	0V2244	N/A	N/A	N/A	N/A	N/A	N/A

\* Denotes replaced Disks at this shop visit.

Remarks: All data provided by Customer

Prepared by: