



AVIATION ENGINE SERVICE, INC.

JET ENGINE OVERHAUL P&W JT3D - JT8D

FAA Approved Repair Station No. ENVR123K - EASA.145.4204

Venezuela INAC Approved Repair Station TMAV-E # 254

Argentina DNA Approved Repair Station No. 1-B-371

8050 N.W. 90th Street, Miami, Florida 33166

ENGINE LIFE LIMITED COMPONENT RECORD

WORK ORDER 6323	MODEL JT8D-15	ESN 687620	DATE July 8, 2009
TOTAL TIME 62,321.06	CUSTOMER M.C.A.		TOTAL CYCLES 34,866

N-1 COMPRESSOR DISKS

STG	PART NUMBER	SERIAL NUMBER	LIMIT HRS	TOTAL HOURS	REMAIN HOURS	LIMITS CYCLES	TOTAL CYCLES	REMAIN CYCLES
C-1*	820401	BBDUAY7462	N/A	5,121	N/A	20,000	5,074	14,926
C-2	790832	BBDUAX1063	30,000	9,395	20,605	20,000	5,517	14,483
C-3*	799773	BBDUAX3632	30,000	5,187	24,813	20,000	7,347	12,653
C-4*	799504	BBDUAY7947	30,000	5,187	24,813	20,000	7,347	12,653
C-5*	745705	BBDUAY8538	30,000	5,187	24,813	20,000	7,347	12,653
C-6*	745706	BBDUAY9123	30,000	5,187	24,813	20,000	7,347	12,653

N-2 COMPRESSOR DISKS

C-7*	815607	BENCAP2455	30,000	5,187	24,813	20,000	7,347	12,653
C-8*	815708	BENCAR3496	30,000	5,187	24,813	20,000	7,347	12,653
C-9*	815609	BENCAS4210	30,000	5,187	24,813	19,000	7,347	11,653
C-10*	815610	BENCAR6844	30,000	5,187	24,813	20,000	7,347	12,653
C-11*	815611	BENCAR8926	30,000	5,187	24,813	20,000	7,347	12,653
C-12*	815612	BENCAR4538	30,000	5,187	24,813	20,000	7,347	12,653
C-13*	5003613-01	S71817	30,000	13,209	16,791	20,000	11,390	8,610

TURBINE DISKS

T-1*	5004301-01	S89565	30,000	13,209	16,791	20,000	11,390	8,610
T-2*	803122	BLDLB41236	30,000	5,187	24,813	20,000	7,347	12,653
T-3*	795603	S49982	30,000	13,209	16,791	20,000	11,390	8,610
T-4*	769104	P04520	30,000	13,209	16,791	20,000	11,390	8,610

* Denotes replaced Disks at this shop visit.

Remarks: All data provided by Customer

AS/B 6431 Due 7/15/2013

Prepared by: